



② Asbest

A close-up photograph of a rectangular sample of asbestos material. The sample is primarily yellow with irregular black and dark grey patches, suggesting a mineral composition like chrysotile. It is resting on a dark, textured surface.

Asbest

A photograph of an empty room with white walls and a brown floor. The room appears to be in poor condition, with visible stains and discoloration on the walls and floor. There is a doorway in the background leading to another room. The lighting is somewhat dim, and the overall atmosphere is one of neglect and decay.

Asbest

Plangrundlage von

Maßstab	Datum 18.11.2025
Anlage	Version